

**From:** [Vojik, Matthew](#)  
**To:** [ben.nelson@thekag.com](mailto:ben.nelson@thekag.com)  
**Cc:** [Levo, Brian](#); [Kenknight, Jeff](#); [Rife, Annette M.](#); [Contreras, Peter](#); [Stephenson, Rachel S.](#); [SEBE461@ECY.WA.GOV](mailto:SEBE461@ECY.WA.GOV); [MikeT@FrogEnv.com](mailto:MikeT@FrogEnv.com)  
**Subject:** NPDES Compliance Evaluation Inspection at KAG West  
**Date:** Friday, June 7, 2019 3:26:44 PM  
**Attachments:** [Report WAR305116 2019-3-29.pdf](#)  
[image002.png](#)

---

**UNITED STATES ENVIRONMENTAL PROTECTION AGENCY  
REGION 10**

1200 Sixth Avenue, Suite 155  
Seattle, Washington 98101-3140

ENFORCEMENT &  
COMPLIANCE ASSURANCE  
DIVISION

-  
  
Ben Nelson  
Terminal Manager  
[ben.nelson@thekag.com](mailto:ben.nelson@thekag.com)

Re: NPDES Compliance Evaluation Inspection at KAG West located at 401 E. Alexander Ave in Tacoma, WA

Dear Mr. Nelson:

On March 29, 2019, the United States Environmental Protection Agency (EPA) conducted a compliance inspection at your facility. The purpose of the inspection was to determine compliance with the Clean Water Act (CWA), specifically, compliance with the facility's National Pollutant Discharge Elimination System (NPDES) Permit No. WAR305116. A copy of the inspection report is attached to this email. Please review the inspection report, note the areas of concern (if any), and take any actions necessary to ensure compliance with the CWA.

An EPA Compliance Officer will use this inspection report in evaluating your facility's compliance with the CWA. This may result in subsequent contact from EPA personnel if a violation is identified. This message is sent only to transmit the inspection report, and it should not be interpreted as a final compliance determination. Please direct any questions regarding compliance evaluation to Brian Levo at [levo.brian@epa.gov](mailto:levo.brian@epa.gov).

Thank you for the cooperation and assistance extended to EPA personnel during the inspection.

Sincerely,

/s/

Matt Vojik  
NPDES Compliance Inspector

Attachments:

1. Inspection Report

cc: Brian Levo  
NPDES Enforcement Coordinator